

ਪੰਜਾਬ ਵਾਟਰ ਸਪਲਾਈ ਅਤੇ ਸੀਵਰੇਜ਼ ਬੋਰਡ  
ਪਲਾਟ ਨੰ: 1 ਬੀ, ਸੈਕਟਰ- 27 ਏ, ਚੰਡੀਗੜ੍ਹ।

ਵਿਖੇ

ਮੁੱਖ ਇੰਜੀਨੀਅਰ(ਪੁਰਵ)।  
ਪੰਜਾਬ ਵ/ਸ ਅਤੇ ਸੀਵਰੇਜ਼ ਬੋਰਡ,  
ਪਟਿਆਲਾ ।



ਨੰਬਰ-ਪਵਸਸਬ-2018/ਵ-3/ 20 640

ਮਿਤੀ: 12-11-18

ਵਿਸ਼ਾ:- ਸ੍ਰੀ ਰਾਜਹੰਸ ਦਾ ਈ-ਮੇਲ- ਸੀਵਰ ਦੀ ਸਮਸਿਆ ਦਾ ਹੱਲ ਕਰਨ ਸਬੰਧੀ।

ਹਵਾਲਾ:- ਇਸ ਦਫਤਰ ਦਾ ਈ-ਮੇਲ ਮਿਤੀ: 03.10.2018, ਦੀ ਲਗਾਤਾਰਤਾ ਵਿੱਚ।

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਹਵਾਲੇ ਅਧੀਨ ਈ-ਮੇਲ ਦੀ ਨਕਲ ਆਪ ਜੀ ਨੂੰ ਭੇਜਦੇ ਹੋਏ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਵਿਸ਼ੇ ਅੰਕਿਤ ਮਾਮਲੇ ਸਬੰਧੀ ਕੀਤੀ ਗਈ ਕਾਰਵਾਈ ਸਬੰਧੀ ਢੁਕਵਾਂ ਜਵਾਬ ਸਿੱਧੇ ਤੌਰ ਤੇ ਪ੍ਰਾਰਥੀ ਨੂੰ ਭੇਜਦੇ ਹੋਏ ਇਸ ਦਫਤਰ ਨੂੰ ਸੂਚਿਤ ਕੀਤਾ ਜਾਵੇ ਜੀ।  
ਨੱਥੀ/ਉਕਤ ਅਨੁਸਾਰ

  
ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ(ਵ) 

Subject: Fwd: Sir

To: Mohit Verma <eep1.pwssb@punjab.gov.in>  
K.P. Goyal <cee.pwssb@punjab.gov.in>

XEN-Pat I, CE

Date: 10/03/18 12:06 PM

From: "Vikas Dhawan" <complaint.pwssb@punjab.gov.in>

Handwritten notes and signatures in the top right corner, including a large 'X' and some illegible scribbles.

The complaint received via trailing e-mail. You are requested to satisfy the Complainant and revert back this e-mail.

Handwritten notes on the right side of the page, including '2-TTT 3/10', 'R.K. 4/10', and '5/11/18'.

----- Original Message -----

From: 2012rajhans <2012rajhans@gmail.com>  
Date: Sep 29, 2017 8:59:19 AM  
Subject: Sir  
pwssb@punjab.gov.in

I belongs to rajpura. one shaft(vent pipe) is in damaged conditions. This can be collapsed in any time We had written to the local authorities also but no action taken  
2 main sewer line had blocked. The sewermans had broken the man hole and diverted the sewage water to the wrong side in the shaft duct so there is sewer plomblens occured in this area mostly  
Hans raj H no.F-1/15 patel colony rajpura town mob.no.7880066127

Sent from my Samsung Galaxy smartphone.