


Mob: - 98726-76755
98881-51208

NEM KUMAR BANSAL

Z-4, H.No. 05678, Street No. 9/1, Namdev Marg Bathinda

To

The Executive Engineer
Pb. W/S & Sew. Div. No. 2
Bathinda.



Sub:

Inspection of Material
Distribution system & Sewerage System, Rising Main, Pumping Machinery,
Head Works Pipe Line, Boundary wall at Water Works Gidderbaha

It is requested that the above said work has been allotted to me vide your office

Letter No. 45 dated 07.01.2019. You are requested to depute the officer / Third party i.e. SGS India Private Limited Kolkata, 700160 for the inspection of material in the factory premises (detail given below). The inspection may be carried out as per specifications attached herewith.

Sr. No.	Description	Qty.	Place
1	100mm i/d DI K-7 ISI 8329:2000 pipe	4960 Mtr.	Jai Balaji Industry Limited, Durgapur West Bengal Mr. Sandeep Saini - 94165-93384
2	150mm i/d DI K-7 ISI 8329:2000 pipe	1950 Mtr.	----do----
3	250mm i/d DI K-7 ISI 8329:2000 pipe	250 Mtr.	----do----
4	300mm i/d DI K-7 ISI 8329:2000 pipe	96 Mtr.	----do----
5	600mm i/d DI K-7 ISI 8329:2000 pipe	4634 Mtr.	----do----
6	800mm i/d RCC Pipe P-1 ISI 458:2003 pipe with rubber Ring	300 Nos.	Garg Pipe Industry, village Bir Kalan, Near Cheema Mandi Distt. Sangrur. Mr. Pardeep- 94171-08081

For Nem Kumar Bansal Cont.

Nem

Prop./PA